

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1	BRS	(trench with capacitor) and (leakage with current)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/09 15:31		
2	BRS	((trench with capacitor) and (leakage with current)) and (parasitic with transistor)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 17:49		
3	BRS	((trench with capacitor) and (leakage with current)) and (parasitic with transistor) and (doping with (borosilicate or BSG))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 17:51		
4	BRS	(trench with capacitor) and (leakage with current) and (doping with (borosilicate or BSG))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 17:54		

Type	Hits	Search Text	DBs	Time Stamp	Comment	Error Definition
5	BRS 20	(trench with capacitor) and (doping with (borosilicate or BSG))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/08 17:54		
6	BRS 2284	257/68,71,301,304,305, 905.ccls. or 438/243-247,249,386,38 7.389,390,392.ccls.	USPAT; US-PGPUB	2004/06/09 15:35		
7	BRS 188	(257/68,71,301,304,305 ,905.ccls. or 438/243-247,249,386,38 7.389,390,392.ccls.) and (borosilicate or BSG)	USPAT; US-PGPUB	2004/06/09 15:35		